

**Product Line** 

Stripspeed™

## Description

Developed to help Propspeed applicators to prepare metal surfaces for reapplication, Stripspeed removes foul-release coatings in 30 minutes or less\*. The thick consistency easily hangs on vertical and overhead surfaces, making it easy to use and there is no mixing required. Just shake, pour and go. Stripspeed is non-flammable, non-caustic, methylene chloride and N-methyl-2-pyrrolidone free.

\*Timing is subject to atmospheric conditions. Ideal temperature is 15-27°C (60-80°F).

## **Typical Uses**

As a coating remover for Propspeed and like systems on metal substrates.

Solvent - Aromatic Blend
Physical state - Gel/Liquid
Appearance - Creamy
Odour - Vinegar
Theoretical coverage - 2m²/Lt
Shelf life - 24 months
pH - Acidic

VOC - 768 g/L (6.41 lb/US Gal) as supplied (EPA

Method 24). These may be subject to variation due to manufacturing tolerances.

# Typical Preparation & Application

See application video at <a href="https://www.propspeed.com/products/stripspeed/how-to-apply">www.propspeed.com/products/stripspeed/how-to-apply</a>

Personal protective equipment (PPE) must be **worn at all times** (refer to SDS).

# STEP 1: SURFACE PREPARATION

- Ensure the metal substrate is free of all growth using a putty knife or rag to remove any fouling.
- The surface being treated must be dry and free of water to optimise efficiency.

#### STEP 2: APPLICATION

- Shake Stripspeed well before use.
- Pour Stripspeed into a mixing tray or other container.
- Apply the product using a brush, ensuring a generous layer (≥2mm) is evenly applied.
- Make sure there are no heavy runs or sags. You'll have 5 to 10 minutes to touch these up.

Product name: Stripspeed

• Leave Stripspeed™ for 20-30 minutes. Do a test patch to see if it is ready for removal. Both the Clear Coat and Etching Primer bases should become weak and, be easily scratched away.

#### STEP 3: REMOVAL

- Remove the product using a paint scraper. For any tricky areas, use a Brass wire brush or scotch-brite pad.
- Any remaining Etching Primer can be easily removed with a Propclean wipe.
- Wash remaining residue with water, scotch-brite and a rag.
- It is not recommended to hose or water blast Stripspeed to avoid splashback on the hull or the product entering waterways.

Touch up any missed areas with Stripspeed, repeating the same application process.

#### **Performance & Limitations**

#### Performance

- In hotter climates (>30°C / 86°F) Stripspeed needs to be reapplied approximately every 10 minutes to ensure the surface stays 'wet'
- Removes Propspeed etching primer and topcoat in one-step in 30 minutes or less\*.

#### Limitations

- Metal substrate must be completely dry before application, water contact will decrease the efficiency of Stripspeed.
- Avoid allowing Stripspeed to dry out, remove product while it is still wet.
- In hotter climates (>30°C / 86°F) it has been observed that Stripspeed can become slightly thin.
- In some cases, Stripspeed dries as a white cast. This can usually be removed with a rag, water, Propclean, acetone or a light hand sand with 80-grit sandpaper.
- Do not use Stripspeed on any substrate that is not metal, including hulls.

# **Health & Safety**

#### Stripspeed

Use full length PVC gloves. Use safety glasses to avoid contact of product with eyes. Always ensure adequate ventilation during application. When adequate ventilation is not available use a solvent respirator (refer to SDS).

Transport	UN No.:	3265
	Class:	8
	Packing Group	II

## Storage

Store locked up in a well-ventilated place. Keep container tightly closed.

If swallowed Immediately call a POISON CENTER doctor/physician. Rinse mouth with water. Do NOT induce vomiting.

Skin contact Rinse skin with water/shower.

Eye contact Rinse cautiously with water for several minutes. Seek

medical attention.

Remove to fresh air. Seek medical attention. Inhalation

Product name: Stripspeed Date of revision: 2022-16-12

<sup>\*</sup>Timing is subject to conditions. Ideal temperature is 15-27°C (60-80°F).